



**BULL MOOSE TUBE COMPANY**

1819 Clarkson Road, Suite 100 • Chesterfield, Missouri 63017  
(636) 537-2600 • [www.bullmoosetube.com](http://www.bullmoosetube.com)

May 29, 2007

Subject: EDDY-GUARD II

Bull Moose Tube Company hereby certifies to the purchaser of Eddy Pipe consisting of sizes 4.50" O.D. and below, that is manufactured in Casa Grande, AZ facility; Gerald, MO facility; Masury, OH facility has been treated with Eddy Guard II.

Sprinkler pipe treated with Eddy Guard II, based upon independent laboratory tests, is resistant to bacteriological growth and maintained minimal bacterial count after multiple flushes of the pipe.

Sincerely,  
Mark Abernathy  
Manager of Engineered Sales